



corrugated steel sheeting
on timber frame placed over
original timber structure

original turned glazed roof tile remains

D
hopper head missing

lead box gutter
defective, requires repairs

rain water system
defective

ROOF PLAN

The Main Guard
13, John Mackintosh Square,
Gibraltar.
Headquarters for the Gibraltar Heritage Trust
Repairs, Additions and Alterations
Drg No 7
SURVEY
Roof Plan
scale 1: 50. date May 2007
J. S. Langdon BArch.